

peupe a +1G40/J1
borne de secours/J1

-S40/1B.2.A1 L1 /
-S40/1B.2.A2 L2 /
-S40/1B.2.A3 L3 /

protection moteur
protection du moteur

protection thermistance
protection thermistor

marche
ligado

arrêt
parada

triangle
conexão Delta

-1FU/1/2A.2.1

C / L

